

General information:



Do not cut the power supply from the camera during firmware upgrade. It's possible to damage the camera by this. The firmware update process can take up to 5 minutes.

1. **First save the camera settings to a file before firmware update.**
2. **After successful update please restore the camera setting to camera default.**
3. **Please delete the browser cache of your internet browser.**
4. **Please restart the camera.**
5. **Import the previously saved settings.**

Compatible models:

TVIP11000, TVIP11050, TVIP11500, TVIP11501, TVIP11550, TVIP11551
TVIP21000, TVIP21050, TVIP21500, TVIP21501, TVIP21550, TVIP21551
TVIP31000, TVIP31050, TVIP31500, TVIP31550, TVIP51500, TVIP51550,
TVIP71500, TVIP71550

Changes to previous version:

- 1) Improved W-LAN "mixed mode" function (Stability and performance of connection)
- 2) Solved FTP picture transmission problems with W-LAN mode
- 3) SD card function does not produce error in log files ("SD record fail" , "SD alarm fail")
- 4) Due to incompatibility problems with different authentication WLAN modes only following combinations are allowed :
 - WPA with TKIP
 - WPA2 with AES
- 5) Direct playback of media with file manager (SD card ...) works with Internet Explorer 9.